

**hp download driver sp72220.exe**



Hp download driver sp72220.exe.

TITLE: Kionix G-Sensor Enabling Driver VERSION: 1.00 REV: A PASS: 1.

DESCRIPTION: The Kionix G-Sensor Enabling Driver enables the accelerometer sensor that provides the rotational control functionality typically used in tablets and cellular phones. This package is provided for supported notebook models running a supported operating system.

PURPOSE: Routine SOFTPAQ FILE NAME: SP72220.exe SOFTPAQ MD5: 8700872293fdd7d6f1d4a67340524dd7 SUPERSEDES: None EFFECTIVE DATE: July 30, 2015 CATEGORY: Firmware SSM SUPPORTED: Yes.

PRODUCT TYPE(S): Notebooks HARDWARE PRODUCT MODEL(S): HP Stream 7 Tablet HP Stream 8 Tablet.

OPERATING SYSTEM(S): Microsoft Windows 10 32.

DEVICES SUPPORTED: Kionix KXCJ9 Accelerometer SPB.

HOW TO USE: 1. Download the file by clicking the Download or Obtain Software button and saving the file to a folder on your hard drive (make a note of the folder where the downloaded file is saved).

2. Double-click the downloaded file and follow the on-screen instructions.

HP Stream 7 Tablet 5701 Kionix G-Sensor Firmware 1.00 Rev.A for Windows 10.

1. Save the driver files to your computer. 2. Run the executable or extract the installation files to a location on your disk. 3. Follow the steps displayed by the setup wizard. 4. After installation, restart the computer.

Important notes:

- Before installation, save all your work and close all the running programs, as the installation may interfere with other apps; - If the setup wizard requests Administrative rights, make sure to run the setup as Administrator; - Pay attention to all installation instructions to make sure the driver is installed correctly;

About General Drivers:

If you install this package, your device will be properly recognized by compatible systems, and might even benefit from new features or various bug fixes.

Please note that, even though other operating systems might also be compatible, we do not recommend you apply any software on platforms other than the specified ones. Doing so might cause the installation to crash, which could even render the device unusable.

When it comes to installing the package, the steps should not be much of a hassle because each manufacturer tries to make them as easy as possible; usually, you must make check for compatibility, get the package, run the available setup, and follow the instructions displayed on-screen.

However, due to the large number of devices out there and the various ways for applying these packages, it would be best if you refer to the installation manual first, to be sure of a successful update.

That being said, click the download button, and apply the present software on your product. Also constantly check with our website to stay up to speed with latest releases.

It is highly recommended to always use the most recent driver version available.

Try to set a system restore point before installing a device driver. This will help if you installed an incorrect or mismatched driver. Problems can arise when your hardware device is too old or not supported any longer.

Missing Windows 10 device driver.

After performing a clean Windows 10 install on my HP Stream 8 Tablet - 5801, device manager lists an unknown device with a location 'on I2C Controller'. I don't seem to be having any issues with the tablet, but would like to resolve this before I run into any problems. Where can I find this driver?

Tags:

08-24-2016 07:43 AM.

Mark as New Bookmark Subscribe Email to a Friend.

See if Windows Update can find the driver for you.

Be connected to the internet.

Go to the device manager and click on the unknown device needing the driver.

Click on the driver tab, click on Update driver.

Select the Search automatically for updated driver software option and see if windows update finds and installs a driver for that device. The search may take several minutes and windows will either find the driver or report that it cannot.

If it cannot, please post the hardware ID for the unknown device.

To find the hardware ID click on the unknown device. The click on the details tab at the top of the unknown device window.

Now you will see a Property drop down list, and it will be set to device description.

Hp download driver sp72220.exe.

Resolve Windows 10 related issues for your HP computers or printers by HP Windows 10 Support Center.

Resolve Windows 10 related issues for your HP computers or printers by HP Windows 10 Support Center.

HP Community > Notebooks > Notebook Operating System and Recovery > Unknown Device and Driver Not Available.

Mark Topic as New Mark Topic as Read Float this Topic for Current User Bookmark Subscribe Mute.

Create an account on the HP Community to personalize your profile and ask a question.

« Previous 1 ... 5 6 7.

All forum topics Previous Topic Next Topic.

10-15-2015 03:51 PM.

Mark as New Bookmark Subscribe Email to a Friend.

Absolutely, what ever is more comfortable to you.

Let me know how it turns out.

10-15-2015 03:55 PM.

Mark as New Bookmark Subscribe Email to a Friend.

I searched "This PC" for sp72320. All it returned was the sp72320.exe downloaded file.

10-15-2015 04:34 PM.

Mark as New Bookmark Subscribe Email to a Friend.

Hmmm Strange. Well in that case we can still extract that folder using 7zip. and it will extract the folder and files that we can use. Download 7zip and then write click on the program, and extract to 'sp72320' and it will make the folder for you.

10-15-2015 07:15 PM.

Mark as New Bookmark Subscribe Email to a Friend.

I extracted from Downloads\HP Downloads "Realtek Local Area Network (LAN) Driver - sp72320.exe" using 7zip (never used this kind of zip extraction software before) and it created a folder named "Realtek Local Area Network (LAN) Driver - sp72320".

I moved it to C:\ProgramData\Package Cache.

I right clicked on Network Adapters / Realtek PCIe GBE Family Controller / Update Driver Software.

and browsed in my computer to the Realtek folder in Package Cache (I also checked the "include subfolders" box).

I got this message: "Windows has determined the driver software for your device is up to date."

10-15-2015 08:02 PM.

Mark as New Bookmark Subscribe Email to a Friend.

Ok, I thought this may be the outcome. So there is only one last thing you can has the possiblity of resolving the issue. You can try downloading the driver directly from the manufacturer which may or may not be a more updated version of the realtek driver. If that does not work then the solution is most like that realtek needs to write a new driver for windows 10 before the issue is resolved.

10-15-2015 08:15 PM.

Mark as New Bookmark Subscribe Email to a Friend.

I appreciate all of your help and effort you have put into this.

How do you know that this unknown driver is related to Realtek?

Can you give me a better link to update the BIOS?

10-15-2015 08:20 PM - edited 10-15-2015 08:21 PM.

Mark as New Bookmark Subscribe Email to a Friend.

I know from reading articles of others that are showing the same device. And its not just realtek, its also the other network adapters from intel, and qualcomm as well. So I think this may be a new device that is utilized by windows 10 in some way but im not entirely sure. What I do know is that it does not appear to causing any issues for the computers that this is showing up on. So I think as long as you are not having any usage or functionality issues with your PC you should not be too alarmed at the moment. I will post a new link to the drivers page here in a moment.

CyberLink software on Windows 10.

My HP500 Pavilion has been delivered with Windows 8 and CyberLink applications a few years ago.

After the upgrade to Windows 10 the CyberLink applications cannot be installed anymore (PowerDirector, PhotoDirector, and PowerDVD).

Is there a way to use the OEM licenses for CyberLink on Windows 10 as well?

Thanks in advance,

Tags:

03-26-2017 09:03 AM.

Mark as New Bookmark Subscribe Email to a Friend.

Sorry, but I don't have very good news for you .

HP will reinstall the preloaded apps when you do a complete factory restore -- but that erases the entire drive, removing everything that is there.

If you provide the detailed product number of your PC, I will see if HP makes that SW available for download.

The product number will be on a tag, similar to one of those below:

\*\*\*If my post helped, click the thumbs-up symbol to say thanks\*\*\*

\*\*\*Please mark Accept As Solution if my post solved your problem\*\*\*

I am a volunteer and I do not work for, nor represent, HP.

03-26-2017 09:21 AM - edited 03-26-2017 09:22 AM.

Mark as New Bookmark Subscribe Email to a Friend.

Here is the link to the HP CyberlinkPower DVD application, which should work just fine with your upgraded PC.

TITLE: Cyberlink Power DVD.

VERSION: 12.0.4.5913 REV: A PASS: 1 DESCRIPTION: This package provides the Cyberlink PowerDVD application in supported models that are running a supported operating system

PowerDirector: See if this version works for you.

This package provides the Cyberlink PowerDirector Software for supported models running a supported operating system. CyberLink PowerDirector is a video editing software application that transform video footage into HD movies to enjoy or share with others.

PhotoDirector. See if this version works for you.

T his package provides the Cyberlink PhotoDirector Software for supported models running a supported operating system. Cyberlink PhotoDirector provides complete tools to edit and store photographic images.

03-26-2017 09:42 AM.

Mark as New Bookmark Subscribe Email to a Friend.

My product number is: E1G77EA#ABH My model number is: 500-035ed.

As said in the former post: I upgraded to Windows 10. This was shortly after the purchase as soon as the upgrade became GA.

03-26-2017 09:47 AM.

Mark as New Bookmark Subscribe Email to a Friend.

Just a double check before I try to install new software: are these executables for Windows 10 as well, even if the PC was shipped with Windows 8 (a few months before the release date of Windows 10)?

03-26-2017 09:48 AM - edited 03-26-2017 09:50 AM.

Mark as New Bookmark Subscribe Email to a Friend.

You're very welcome.

Yes, those programs are all supported for W10.

I use the PowerDVD on all of my HP PC's that didn't come with W10 and now are all on W10.

The other two, I don't use.

I also use the W10 Cyberlink Power2Go software (for burning DVD's) if you want that too.

03-26-2017 09:56 AM.

Mark as New Bookmark Subscribe Email to a Friend.

Thanks again, the Power2Go executable would be great as well!

Thanks in advance.

03-26-2017 10:00 AM.

Mark as New Bookmark Subscribe Email to a Friend.

CyberLink Power2Go is an media burning software that allows users to burn data, music or video discs. CyberLink Power2Go offers support for CDs, DVDs, HD DVDs, and Blu-ray discs, and also includes features for disc copying. This package is available for supported models running supported operating systems.

8.0.3.6624 Rev.A (15 Nov 2016)

03-27-2017 07:14 AM.

Mark as New Bookmark Subscribe Email to a Friend.

Thanks so much and - given your quick replies - you seem so knowledgeable around HP hardware and OEM software!

At the same time I don't want to install software from FTP sites that are not being suggested on the HP support site. For CyberLink for Windows 10, do you have links that are on the official HP support site?

Reason: today, my alternative solution for Power2Go - which is <http://www.imgburn.com/> - has been identified as potential malicious by Norton Internet Security  I want to avoid this for my CyberLink software, so I only want to download software from <https://> sites.

PS please consider my remarks above as kind and risk avoiding, not as rude. you will understand why